

# Township of Cavan Monaghan

## Alphabetical Road List

Sect. No.	Road Name	From	To	Length (km)	AADT	Preliminary Improvement Type Recommendation	Cost (x1000)	Surface Condition	Structural Adequacy	Condition Rating
1000	Acadia Crt	Valley Rd	South end	0.21	40	ST1 - Single Surface Treatment	\$6	8	15	78
1005	Albert St	Mount Pleasant Rd	Bland Li	0.305	40	Preventative Maintenance	-	9	18	69
1010	Alexander St.	Blue Jay St.	North End	0.09	20	Preventative Maintenance	-	10	19	89
1015	Allen Ln	Needler's Lane	King Street West	0.12	250	PP1 - Pulverize and Pave 1 Lift	\$24	6	10	69
1020	Anne St	Needler's Lane	Cavan Street	0.47	350	Preventative Maintenance	-	9	18	79
1025	Anne St	Cavan Street	South End	0.24	70	Preventative Maintenance	-	10	19	75
1030	Ashley Cres	Cathcart Cres	South End	0.3	40	ST2A - Double Surface Treatment with Granular A	\$28	5	9	68
1035	Ava Cres	Deyell Li	North End	1.41	60	ST2A - Double Surface Treatment with Granular A	\$133	6	11	65
1040	Bank St N	Cty Rd 10	End	0.28	70	PP1 - Pulverize and Pave 1 Lift	\$55	6	12	83
1045	Bank St S	Cty Rd 21	North End	0.19	40	Preventative Maintenance	-	10	19	79
1050	Bartlett Rd	Moncrief Li	Whitfield Rd	1.45	275	ST2A - Double Surface Treatment with Granular A	\$136	6	12	65
1055	Baxter Creek Crt N	Brook Street	South End	0.1	25	Preventative Maintenance	-	8	16	92
1060	Beardsmore Dr	Cnty Rd 11	Johnston Dr	1.55	400	ST1 - Single Surface Treatment	\$43	8	17	67
1065	Bee Dr	Deyell Li	South End	0.705	45	Preventative Maintenance	-	9	18	70
1070	Best Rd	Mount Pleasant Rd	Hayes Li	1.42	37	G - Gravel (75mm)	\$30	9	18	67
1085	Bland Li	Jones 1/4 Line	2500m East	2.5	222	ST1 - Single Surface Treatment	\$70	7	14	63
1080	Bland Li	Albert St	Cty Rd 10	0.08	222	RMP1 - Mill & Pave, 1 Lift	\$26	7	14	77
1075	Bland Li	925m East	Albert St	0.925	222	ST1 - Single Surface Treatment	\$26	8	15	77
1090	Bland Li	Jones 1/4 Line	1850m West	1.85	150	G - Gravel (75mm)	\$38	8	15	75
1095	Blue Jay St.	County Rd 10	Alexander Dr	0.22	30	Preventative Maintenance	-	10	19	89
1100	Brackenridge Dr	Deyell Li	Carmel Li	1.33	212	Preventative Maintenance	-	9	17	78
1105	Brewda Cres	Kalman Dr	East End	0.11	35	PP1 - Pulverize and Pave 1 Lift	\$22	6	12	71
2220	Bromont Dr	Fallis Li	Horizon Ave	0.11	400	Preventative Maintenance	-	10	20	100
2225	Bromont Dr	Horizon Ave	Northhill Ave	0.09	400	Preventative Maintenance	-	10	20	100
2230	Bromont Dr	Northhill Ave	Pristine Trail	0.09	250	Preventative Maintenance	-	10	20	100
2235	Bromont Dr	Pristine Trail	Highlands Blvd	0.12	250	Preventative Maintenance	-	10	20	100
1110	Brookside St	Cnty Rd 10	Cnty Rd 10	0.86	275	Preventative Maintenance	-	9	17	95
1120	Brown Li	Elmdale Rd	Country Rd 11	1.76	417	ST2A - Double Surface Treatment with Granular A	\$166	6	11	59
1115	Brown Li	Hwy 7	Elmdale Rd	1.8	440	ST1 - Single Surface Treatment	\$50	7	14	63
1125	Brown Li	Cty Rd 11	East End	0.53	40	ST2A - Double Surface Treatment with Granular A	\$50	5	8	67
1130	Buckland Dr	Cty Rd 10	East End	0.2	40	ST1 - Single Surface Treatment	\$6	7	14	62
1135	Burnham Crt	McGuire Dr	North End	0.055	40	Preventative Maintenance	-	8	17	92
1140	Campbell Av	Longview Dr	Longview Dr	1	110	Preventative Maintenance	-	9	17	85
1145	Carmel Cres	Cty Rd 10	West end	0.56	45	Preventative Maintenance	-	9	17	85
1150	Carmel Li	Brackenridge Dr	Cnty Rd 28	3.11	353	ST1 - Single Surface Treatment	\$87	8	15	74
1155	Carmel Li	Brackenridge Dr	Cty rd 10	3.19	322	ST1 - Single Surface Treatment	\$89	8	15	74
1160	Carmel Li	Cty Rd 10	1400m West	1.4	120	ST2A - Double Surface Treatment with Granular A	\$132	6	12	69
1165	Carmel Li	1400m West of Cty Rd 10	West end	1.35	100	ST2A - Double Surface Treatment with Granular A	\$127	6	12	69
1170	Carolyn St	Johnston Dr	South End	0.3	30	ST1 - Single Surface Treatment	\$8	7	14	77
1175	Carveth Dr	Zion Li	Huston Street	1.39	450	Preventative Maintenance	-	9	17	83
1180	Cathcart Cr	Stewart Li	Highway 7	1.15	350	ST2A - Double Surface Treatment with Granular A	\$108	6	10	70
1185	Cavan St	King Street West	Anne St	0.3	110	Preventative Maintenance	-	9	17	81
2110	Cavan Station Rd	Highway 7A	North End	0.44	50	G - Gravel (75mm)	\$9	8	16	82
1190	Cavan Wood Dr	Cnty Rd 10	East End	0.18	45	Preventative Maintenance	-	9	18	86
1195	Cedar Cres	Hutchinson Dr	South End	0.07	5	ST2A - Double Surface Treatment with Granular A	\$7	6	10	61
1200	Cedar Valley Rd	Hutchinson Dr	Cntry Rd 28	3.01	302	ST2A - Double Surface Treatment with Granular A	\$283	6	11	64
1205	Centennial Ln	Cty Rd 10	East End	0.32	800	Preventative Maintenance	-	9	18	96
1210	Centre St	Tupper St	Union Street	0.16	1700	Preventative Maintenance	-	9	17	70
1215	Centre St	Union St	West End	0.44	250	RMP1 - Mill & Pave, 1 Lift	\$141	7	14	76
1220	Century Bv	Centennial Ln	Nina Ct	0.185	450	Preventative Maintenance	-	10	20	100
1225	Challice Li	Cty Rd 10	End	2.05	150	ST1 - Single Surface Treatment	\$57	7	13	76
1230	Charles St	West End	East End	0.145	35	Preventative Maintenance	-	10	20	73
1235	Clifford Li	Highway 7A	East End	1.54	200	ST2A - Double Surface Treatment with Granular A	\$145	6	10	56
1240	Collins Ln	Centre St	North end	0.08	20	G - Gravel (75mm)	\$2	6	12	53
1245	Cora Dr	Sharpe Li	South End	0.37	60	ST2A - Double Surface Treatment with Granular A	\$35	6	11	72
1250	Darling Cres	Stewart Li	South End	0.925	45	Preventative Maintenance	-	9	18	78
1255	Davis Rd	Stewart Li	Maple Grove Rd	1.48	350	ST1 - Single Surface Treatment	\$41	8	16	81
1260	Deer Ave.	Larmer Li	Plains Cl	0.76	200	ST1 - Single Surface Treatment	\$21	8	17	77
1265	Deyell Li	Cnty Rd 10	T-Way Dr	2.11	237	ST2A - Double Surface Treatment with Granular A	\$199	6	9	62
1270	Deyell Li	T-Way Dr	Hutchinson Dr	1.33	182	Preventative Maintenance	-	9	18	77

Sect. No.	Road Name	From	To	Length (km)	AADT	Preliminary Improvement Type Recommendation	Cost (x1000)	Surface Condition	Structural Adequacy	Condition Rating
1275	Distillery St	Needler's Lane	South End	0.16	150	ST2A - Double Surface Treatment with Granular A	\$15	5	7	53
1280	Dobbin Rd	Cnty Rd 15	North End	1.12	500	Recon 1S - Full Reconstruction + 1 Lift	\$591	5	7	66
1285	Dranoel Dr	Dranoel Rd	Highway 7A	0.52	150	Preventative Maintenance	-	9	18	77
1310	Dranoel Rd	Syer Li	South End	1.65	90	G - Gravel (75mm)	\$34	8	16	59
1290	Dranoel Rd	Highway 7A	Morton Li	0.83	251	ST2A - Double Surface Treatment with Granular A	\$78	6	9	63
1300	Dranoel Rd	Morton Li	Sharpe Li	2.02	171	ST1 - Single Surface Treatment	\$57	8	16	74
1305	Dranoel Rd	Sharpe Li	Stewart Li	1.44	108	ST1 - Single Surface Treatment	\$40	8	16	74
1295	Dranoel Rd	Syer Li	Highway 7A	1.28	211	Preventative Maintenance	-	10	19	81
1315	Dufferin St	Gravel Rd	End	0.15	390	ST2A - Double Surface Treatment with Granular A	\$14	6	7	67
1320	Eagleson Li	McCamus 1/4 Line	Cty Rd 28	2.85	136	ST2A - Double Surface Treatment with Granular A	\$268	6	10	62
1325	Eagleson Li	McCamus 1/4 Line	Cty Rd 10	3	55	ST2A - Double Surface Treatment with Granular A	\$282	6	10	61
1330	Edgewood Park Dr	Mount Pleasant Rd	North End	0.52	175	Preventative Maintenance	-	8	16	82
1335	Edgewood Park Dr	Loop	Loop	0.48	150	Preventative Maintenance	-	8	16	82
1340	Elgar Dr	Zion Li	White Birch rd	0.74	125	ST2A - Double Surface Treatment with Granular A	\$70	6	10	64
1345	Elgar Dr	White Birch Rd	South End	0.48	125	Preventative Maintenance	-	10	20	81
1350	Elizabeth St	King George St	Miller St	0.12	20	ST1 - Single Surface Treatment	\$3	7	14	59
1355	Elmdale Rd	Brown Li	Cnty Rd 15	1.4	350	ST2A - Double Surface Treatment with Granular A	\$132	6	9	62
1360	Fallingbrook Dr	Poplar Plains Dr	Cavan Wood Dr	0.115	45	Preventative Maintenance	-	9	18	86
1365	Fallis Li	Tapley 1/4 Line	Highlands Blvd	2.95	527	Preventative Maintenance	-	9	18	69
1375	Fallis Li	Tapley 1/4 Line	West End	3.89	240	ST1 - Single Surface Treatment	\$109	8	16	80
1370	Fallis Li	Highlands Blvd	Cty Rd 10	0.53	495	Preventative Maintenance	-	10	20	100
2160	Fernridge Heights	Highlands Blvd	Northhill Ave	0.31	150	Preventative Maintenance	-	10	20	100
1380	Filman Cr	Longview Dr	Longview Dr	0.38	75	Preventative Maintenance	-	8	16	82
1385	Ford Cres	Highway 7A	East End	1.37	100	PP1 - Pulverize and Pave 1 Lift	\$272	6	12	73
1390	Ford Dr	Highway 7A	South End	0.74	100	PP1 - Pulverize and Pave 1 Lift	\$147	6	12	73
1396	Frederick St	Main St	West End	0.12	75	Preventative Maintenance	-	10	19	99
1395	Frederick St	Main St	Anne St	0.41	260	ST2A - Double Surface Treatment with Granular A	\$39	5	7	65
1400	George St	Cnty Rd 21	South End	0.23	60	Preventative Maintenance	-	10	19	99
2098	Glamorgan Rd	South End	Zion Li	1.11	50	G - Gravel (75mm)	\$23	8	16	79
2095	Glamorgan Rd	Fallis Road	County Rd 21	1.06	50	G - Gravel (75mm)	\$22	8	16	81
2096	Glamorgan Rd	County Rd 21	North End	0.17	50	ST2A - Double Surface Treatment with Granular A	\$16	6	12	71
1405	Gravel Rd	King St E	End	0.3	400	ST1 - Single Surface Treatment	\$8	7	13	51
1410	Hay St	Anne St	King Street West	0.095	595	Preventative Maintenance	-	9	17	85
1420	Hayes Li	Cnty Rd 10	Howden 1/4 Unopened	3.5	284	Preventative Maintenance	-	9	17	75
1415	Hayes Li	Howden 1/4 Unopened	Highway 7	2.8	559	Preventative Maintenance	-	9	17	83
1430	Hayes Li	1500 East of Cty Rd 38	Jones 1/4 Li	1.84	207	ST1 - Single Surface Treatment	\$52	8	15	79
1425	Hayes Li	Jones 1/4 Line	Cnty Rd 10	3.5	252	Preventative Maintenance	-	10	19	80
1440	High St	Mill St	North End	0.465	15	G - Gravel (75mm)	\$10	6	11	56
2115	Highlands Blvd	Fallis Li	Fernridge Heights	0.11	400	Preventative Maintenance	-	10	20	100
2120	Highlands Blvd	Fernridge Heights	Northhill Ave	0.09	400	Preventative Maintenance	-	10	20	100
2125	Highlands Blvd	Northhill Ave	Pristine Trail	0.09	250	Preventative Maintenance	-	10	20	100
2130	Highlands Blvd	Pristine Trail	Timber Dr	0.24	250	Preventative Maintenance	-	10	20	100
2135	Highlands Blvd	Timber Dr	Station Dr	0.09	250	Preventative Maintenance	-	10	20	100
2140	Highlands Blvd	Station Dr	Melrose Dr	0.09	250	Preventative Maintenance	-	10	20	100
2145	Highlands Blvd	Melrose Dr	Bromont Dr	0.12	250	Preventative Maintenance	-	10	20	100
2150	Highlands Blvd	Bromont Dr	Horizon Ave	0.1	150	Preventative Maintenance	-	10	20	100
2155	Highlands Blvd	Horizon Ave	Horizon Ave	0.29	150	Preventative Maintenance	-	10	20	100
1445	Highview Cres	Syer Li	North End	0.7	45	ST1 - Single Surface Treatment	\$20	7	13	76
1450	Hillview Dr	South End	North End	0.925	115	ST2A - Double Surface Treatment with Granular A	\$87	5	9	61
2085	Hogsback Rd	Ski Hill Rd	South End	0.3	50	G - Gravel (75mm)	\$6	8	16	81
1455	Hooton Dr	Fieldview Dr	Preston Rd	0.3	408	ST1 - Single Surface Treatment	\$8	7	13	61
1470	Hooton Dr	County Rd 10	2480m East	2.48	71	G - Gravel (75mm)	\$52	6	10	51

Sect. No.	Road Name	From	To	Length (km)	AADT	Preliminary Improvement Type Recommendation	Cost (x1000)	Surface Condition	Structural Adequacy	Condition Rating
1460	Hooton Dr	1500m East	Fieldview Dr	2.52	150	ST1 - Single Surface Treatment	\$71	7	13	69
1465	Hooton Dr	2480m East	1500m East	1.52	71	Preventative Maintenance	-	9	17	70
2205	Horizon Ave	Bromont Dr	Highlands Blvd	0.14	150	Preventative Maintenance	-	10	20	100
2210	Horizon Ave	Highlands Blvd	Northhill Ave	0.04	150	Preventative Maintenance	-	10	20	100
2215	Horizon Ave	Northhill Ave	Highlands Blvd	0.15	150	Preventative Maintenance	-	10	20	100
1485	Howden 1/4 Li	Sharpe Li	South End	0.14	20	G - Gravel (75mm)	\$3	8	15	63
1475	Howden 1/4 Li	Sharpe Li	Stewart Li	1.45	121	ST2A - Double Surface Treatment with Granular A	\$136	6	10	64
1480	Howden 1/4 Li	Stewart Li	Hooton Dr	1.45	90	Preventative Maintenance	-	9	17	77
1490	Hunter St	Queen St	Turner St	0.26	80	Preventative Maintenance	-	10	19	76
1495	Huston St	Carveth Dr	King Street West	0.35	400	PP1 - Pulverize and Pave 1 Lift	\$69	6	12	72
1505	Hutchison Dr	Cedar Valley Rd	Larmer Li	1.09	270	ST1 - Single Surface Treatment	\$31	7	13	68
1510	Hutchison Dr	Larmer Li	Syer Li	1.32	211	ST1 - Single Surface Treatment	\$37	7	13	68
1500	Hutchison Dr	Cnty Rd 21	Cedar Valley Rd	1.55	278	ST2A - Double Surface Treatment with Granular A	\$146	6	11	64
1520	Hutchison Dr	Deyell Li	Zion Li	1.51	162	ST1 - Single Surface Treatment	\$42	8	16	73
1515	Hutchison Dr	Zion Li	Cnty Rd 21	1.5	178	ST2A - Double Surface Treatment with Granular A	\$141	5	7	58
1525	Jack Ln	Sharpe Li	North End	0.6	45	ST1 - Single Surface Treatment	\$17	8	15	79
1530	Jill Ln	Stewart Li	South End	0.22	20	Preventative Maintenance	-	9	18	84
1540	Johnston Dr	Worboy Ct	Carolyn St	0.42	400	Recon 1R - Full Reconstruction + 1 Lift	\$222	5	8	52
1535	Johnston Dr	Carolyn St	North End	0.91	400	Recon 1R - Full Reconstruction + 1 Lift	\$480	5	8	60
1545	Jones 1/4 Line	Hayes Li	Bland Li	1.3	98	G - Gravel (75mm)	\$27	8	15	70
1550	Kalman Dr	Carmel Li	South End	0.51	75	PP1 - Pulverize and Pave 1 Lift	\$101	6	12	71
1555	Kennedy Dr	Mount Pleasant Rd	South End	0.62	50	Preventative Maintenance	-	9	18	86
1560	King George St	Cty Rd 10	Elizabeth Street	0.115	45	ST1 - Single Surface Treatment	\$3	7	14	59
1565	Larmer Li	Cnty Rd 10	Hutchinson Dr	3.52	521	Preventative Maintenance	-	10	20	73
1570	Larmer Li	Highway 115	Cnty Rd 10	1.3	397	ST1 - Single Surface Treatment	\$36	8	16	73
1580	Larmer Li	Cty Rd 28	925m West	0.925	342	ST1 - Single Surface Treatment	\$26	8	15	73
1575	Larmer Li	Hutchinson Dr	1820m East	1.82	342	ST1 - Single Surface Treatment	\$51	8	15	73
1585	Larmer Li	Highway 115	Tapley 1/4 Li	2.08	224	Preventative Maintenance	-	10	20	81
1590	Lisa Crt	King Street West	South End	0.22	45	Preventative Maintenance	-	10	20	89
1595	Longview Dr	Cnty Rd 9	North End	0.48	150	Preventative Maintenance	-	8	16	82
1600	Main St	King Street West	South end	0.6	350	Preventative Maintenance	-	10	19	87
1605	Manor Dr	Cnty Rd 10	Union Street	0.175	750	Preventative Maintenance	-	10	20	88
1610	Maple Grove Rd	Preston Rd	Highway 7	0.45	400	RMP1 - Mill & Pave, 1 Lift	\$144	7	13	60
1615	Maple Tree Crt	Pine Tree Court	West End	0.29	45	Preventative Maintenance	-	9	17	74
2105	Maplehill Crt	Maplehill Dr	West End	0.05	50	Preventative Maintenance	-	8	16	82
2100	Maplehill Dr	County Rd 9	South End	0.41	100	Preventative Maintenance	-	8	16	82
1620	Marshall St	West End	East End	0.22	40	Preventative Maintenance	-	10	20	74
1625	McCamus 1/4 Li	Eagleson Li	Carmel Li	1.43	63	G - Gravel (75mm)	\$30	8	16	66
1630	McGuire Dr	Manor Dr	West End	0.47	250	Preventative Maintenance	-	8	16	92
1635	Meadow Ln	Workman St	East End	0.21	30	G - Gravel (75mm)	\$4	7	14	58
2250	Melrose Dr	Pristine Trail	Highlands Blvd	0.16	150	Preventative Maintenance	-	10	20	100
1650	Mervin Li	240m East of Cty Rd 11	East End	0.56	25	G - Gravel (75mm)	\$12	5	8	46
1655	Mervin Li	550m West of Cty Rd 11	West end	1.63	25	G - Gravel (75mm)	\$34	8	16	68
1645	Mervin Li	County Road 11	240m East	0.24	90	Preventative Maintenance	-	9	18	83
1640	Mervin Li	County Road 11	300m West	0.3	150	Preventative Maintenance	-	9	18	85
1660	Mill St	Cnty Rd 10	Workman St.	0.29	45	RO1 - Hot Mix Overlay, 1 Lift	\$53	8	15	62
1665	Mill St	Cty Rd 10	West End	0.15	25	ST2A - Double Surface Treatment with Granular A	\$14	6	12	55
1670	Miller St	Cty Rd 10	South End	0.32	45	ST1 - Single Surface Treatment	\$9	7	13	59
1675	Moore Dr	2440m West of Cty Rd 28	West End	1.7	694	Preventative Maintenance	-	8	16	81
1680	Moore Dr	Cty Rd 28	2440m West	2.44	526	Preventative Maintenance	-	8	16	81
1685	Morningside Pl	Valleyview Drive	End	0.27	90	ST2A - Double Surface Treatment with Granular A	\$25	5	7	58
1710	Morton Li	Dranoel Rd	1550m East	1.55	47	G - Gravel (75mm)	\$32	8	16	62
1705	Morton Li	Cnty Rd 10	2150m West	2.15	165	ST1 - Single Surface Treatment	\$60	8	16	73
1700	Morton Li	Tapley 1/4 Line	1300m East	1.3	165	G - Gravel (75mm)	\$27	8	16	73
1690	Morton Li	Highway 7A	520m West	0.52	254	ST1 - Single Surface Treatment	\$15	7	14	76
1715	Morton Li	Tapley 1/4	2220m West	2.22	47	G - Gravel (75mm)	\$46	8	16	73
1695	Morton Li	520m West	Cnty Rd 10	5.66	196	ST1 - Single Surface Treatment	\$158	8	16	80
2090	Mount Pleasant Rd	County Road 10	High St.	0.13	200	ST1 - Single Surface Treatment	\$4	8	16	66
1720	Needler's Ln	Anne St	Distillery St	0.22	350	Preventative Maintenance	-	8	16	90
1725	Nina Crt	West End	East End	0.23	175	RMP1 - Mill & Pave, 1 Lift	\$74	7	13	87
2165	Northhill Ave	Highlands Blvd	Fernridge Heights	0.23	250	Preventative Maintenance	-	10	20	100
2170	Northhill Ave	Fernridge Heights	Bromont Dr	0.1	250	Preventative Maintenance	-	10	20	100
2175	Northhill Ave	Bromont Dr	Horizon Ave	0.08	250	Preventative Maintenance	-	10	20	100
1730	Pine Tree Crt	Valley Rd	West End	0.19	45	Preventative Maintenance	-	9	17	76
1735	Plains Cl	Deer Avenue	Deer Avenue Loop	0.84	110	ST1 - Single Surface Treatment	\$24	8	16	73

Sect. No.	Road Name	From	To	Length (km)	AADT	Preliminary Improvement Type Recommendation	Cost (x1000)	Surface Condition	Structural Adequacy	Condition Rating
1740	Poplar Plains Dr	Cnty Rd 10	East End	0.18	70	Preventative Maintenance	-	9	18	86
1745	Preston Rd	Stewart Li	Hooton Dr	1.46	461	ST1 - Single Surface Treatment	\$41	7	14	64
1750	Preston Rd	Hooton Dr	Cnty Rd 9	1.52	211	G - Gravel (75mm)	\$32	8	16	81
1755	Prince St	Anne St	South End	0.13	45	Recon 2U - Full Reconstruction + 2 Lifts	\$150	6	9	54
1760	Princess St	Anne St	South End	0.13	45	Preventative Maintenance	-	9	18	69
2185	Pristine Trail	Highlands Blvd	Timber Dr	0.09	250	Preventative Maintenance	-	10	20	100
2190	Pristine Trail	Timber Dr	Station Dr	0.09	250	Preventative Maintenance	-	10	20	100
2195	Pristine Trail	Station Dr	Melrose Dr	0.09	250	Preventative Maintenance	-	10	20	100
2200	Pristine Trail	Melrose Dr	Bromont Dr	0.08	250	Preventative Maintenance	-	10	20	100
1765	Queen St	King Street West	Hunter Street	0.175	85	Preventative Maintenance	-	10	19	84
1770	Rose Cres	Kennedy Dr	South End	0.13	40	Preventative Maintenance	-	9	18	86
1775	Rothesay Av	South End	Lansdowne St W	0.54	125	ST1 - Single Surface Treatment	\$15	7	13	68
1780	Scout Cr	Tapley 1/4 Line	East End	0.22	25	ST1 - Single Surface Treatment	\$6	8	15	69
1790	Sharpe Li	1100m West of Hwy 7	Highway 7	1.1	562	ST1 - Single Surface Treatment	\$31	7	13	61
1810	Sharpe Li	Jack Lane	700m West of Winslow 1/4	1.32	92	ST1 - Single Surface Treatment	\$37	8	15	74
1785	Sharpe Li	Howden 1/4 Li	1100m West of Hwy 7	1.68	562	Preventative Maintenance	-	9	18	85
1815	Sharpe Li	700m West of Winslow 1/4	Winslow 1/4 Li	0.7	92	ST1 - Single Surface Treatment	\$20	8	15	79
1820	Sharpe Li	Dranoel Rd	Jack Lane	1.495	92	ST1 - Single Surface Treatment	\$42	8	15	80
1795	Sharpe Li	Cnty Rd 10	Howden 1/4 Li	3.52	392	Preventative Maintenance	-	9	18	85
1800	Sharpe Li	Winslow 1/4 Li	1780m East	1.78	93	ST1 - Single Surface Treatment	\$50	8	15	81
1805	Sharpe Li	1780m East of Winslow	Cty Rd 10	1.75	93	ST1 - Single Surface Treatment	\$49	8	15	81
1825	Shield's Dr	Bland Line	South End	1.2	45	G - Gravel (75mm)	\$25	7	14	52
1830	Skiview Dr	Hillview Dr	North End	0.37	45	ST2A - Double Surface Treatment with Granular A	\$35	5	6	51
1835	Sowden Ln	Main St	East End	0.13	20	Preventative Maintenance	-	10	20	72
2245	Station Dr	Pristine Trail	Highlands Blvd	0.16	150	Preventative Maintenance	-	10	20	100
1840	Stewart Li	Howden 1/4 Li	Preston Rd	2.82	755	ST1 - Single Surface Treatment	\$79	8	15	65
1845	Stewart Li	Cnty Rd 10	Howden 1/4 Line	3.55	755	ST1 - Single Surface Treatment	\$99	8	15	65
1855	Stewart Li	Cty Rd 10	1040m West of Cty Rd 10	1.04	393	ST2A - Double Surface Treatment with Granular A	\$98	6	12	72
1870	Stewart Li	2850m West of Winslow 1/4	300m West	0.3	254	ST1 - Single Surface Treatment	\$8	8	16	74
1880	Stewart Li	Dranoel Rd	300m East	0.3	254	ST1 - Single Surface Treatment	\$8	8	16	74
1860	Stewart Li	1320 West of Cty Rd 10	2220m West of Cty Rd 10	0.9	393	ST1 - Single Surface Treatment	\$25	8	15	79
1875	Stewart Li	Winslow 1/4 Li	2850m West	2.85	254	Preventative Maintenance	-	10	20	81
1850	Stewart Li	Winslow 1/4 Li	1300m East	1.3	393	Preventative Maintenance	-	9	18	84
1865	Stewart Li	1040m West of Cty Rd 10	1320m West of Cty Rd 10	0.28	393	Preventative Maintenance	-	9	18	84
1885	Sunset Dr	Highway 7A	South End	0.74	90	RMP1 - Mill & Pave, 1 Lift	\$237	7	13	75
1890	Syer Li	Hutchinson Dr	Cnty Rd 28	2.85	633	ST1 - Single Surface Treatment	\$80	8	16	67
1895	Syer Li	Highway 115 Ramp	Hutchinson Dr	3.5	566	ST1 - Single Surface Treatment	\$98	8	16	67
1915	Syer Li	Dranoel Rd	Highview Cres	2.48	90	G - Gravel (75mm)	\$52	8	15	70
1905	Syer Li	Highview Cres	Tapley 1/4 Li	1.18	227	Preventative Maintenance	-	9	18	75
1910	Syer Li	Tapley 1/4 Line	Vista Cres	2.53	201	Preventative Maintenance	-	10	20	81
1900	Syer Li	Vista Cres	Cty Rd 10	1.05	351	Preventative Maintenance	-	9	18	85
1935	Tapley 1/4 Li	Larmer Li	Syer Li	1.33	517	ST2A - Double Surface Treatment with Granular A	\$125	6	10	57
1940	Tapley 1/4 Li	Syer Li	Highway 7A	1.32	453	ST2A - Double Surface Treatment with Granular A	\$124	6	11	58
1920	Tapley 1/4 Li	Highway 115 Ramp	Cnty Rd 21	1.3	858	Preventative Maintenance	-	9	17	69
1925	Tapley 1/4 Li	Highway 115 Ramp	Fallis Li	0.22	858	RMP1 - Mill & Pave, 1 Lift	\$70	7	14	76
1930	Tapley 1/4 Li	Fallis Li	Larmer Li	1.11	655	ST2A - Double Surface Treatment with Granular A	\$104	6	11	72
1945	Tapley 1/4 Li	Highway 7A	Morton Li	1.4	82	ST2A - Double Surface Treatment with Granular A	\$132	6	10	64
1950	Thorne Dr	Deyell Li	Zion Li	1.53	58	G - Gravel (75mm)	\$32	8	16	65
2240	Timber Dr	Pristine Trail	Highlands Blvd	0.16	150	Preventative Maintenance	-	10	20	100
1955	Turner St	Hunter Street	King Street West	0.18	80	ST2A - Double Surface Treatment with Granular A	\$17	5	7	49
1960	T-Way Dr	Deyell Li	South End	0.6	65	Preventative Maintenance	-	9	18	70
1965	Union St	King Street West	Manor Dr	0.22	1400	PP1 - Pulverize and Pave 1 Lift	\$44	6	11	82
1970	Valley Rd	Larmer Li	Tapley 1/4 Li	2.2	185	ST1 - Single Surface Treatment	\$62	7	14	69
1975	Valleyview Dr	Fallis Li East	Morningside Pl	0.75	155	Preventative Maintenance	-	9	18	85
1980	Valleyview Dr	Fallis Li West	Morningside Pl	0.85	155	Preventative Maintenance	-	9	18	85
1985	Vista Cres	Syer Li	North End	0.37	45	ST1 - Single Surface Treatment	\$10	7	14	78
1990	White Birch Rd	Elgar Dr	End	0.85	65	ST2A - Double Surface Treatment with Granular A	\$80	5	6	63
2000	Whitfield Rd	Cty Rd 28	740m East	0.74	375	Preventative Maintenance	-	9	18	86
2020	Whittington Dr	600m East	750m East	0.15	275	Recon 1R - Full Reconstruction + 1 Lift	\$79	6	9	68

Sect. No.	Road Name	From	To	Length (km)	AADT	Preliminary Improvement Type Recommendation	Cost (x1000)	Surface Condition	Structural Adequacy	Condition Rating
2015	Whittington Dr	Elmdale Rd	West End	1.48	350	Preventative Maintenance	-	8	16	79
2005	Whittington Dr	Elmdale Rd	600m East	0.6	275	Preventative Maintenance	-	8	16	79
2010	Whittington Dr	750m East	East End	0.75	210	Recon 1R - Full Reconstruction + 1 Lift	\$396	5	6	63
2025	Wilson Li	West End	1000m West of Cnty Rd 10	1.78	150	ST2A - Double Surface Treatment with Granular A	\$167	6	11	71
2030	Wilson Li	1000m West of Cnty Rd 10	Cnty Rd 10	1	150	ST2A - Double Surface Treatment with Granular A	\$94	6	11	71
2035	Wing St	Bank Street South	East End	0.1	30	Preventative Maintenance	-	10	19	72
2040	Winslow 1/4 Li	Sharpe Li	North End	1.67	61	G - Gravel (75mm)	\$35	8	16	72
2045	Worboy Crt	Beardsmore Dr	West End	0.19	5	G - Gravel (75mm)	\$4	8	16	64
2050	Workman St.	Mount Pleasant Rd	Mill St.	0.19	45	Preventative Maintenance	-	9	17	66
2065	Zion Li	Hutchinson Dr	Cnty Rd 10	3.25	211	ST2A - Double Surface Treatment with Granular A	\$306	6	12	65
2060	Zion Li	Hutchison Dr	Cty Rd 28	2.87	323	ST2A - Double Surface Treatment with Granular A	\$270	6	12	69
2055	Zion Li	Cty Rd 10	Carveth Dr	2.15	433	Preventative Maintenance	-	10	20	70
2075	Zion Li	2500m West of Elgar	Glamorgan Rd	2.5	115	ST1 - Single Surface Treatment	\$70	8	14	71
2070	Zion Li	Elgar Dr	2500m West	2.5	115	ST2A - Double Surface Treatment with Granular A	\$235	6	12	69
2080	Zion Li	Carveth Dr	Elgar Dr	0.35	115	ST2A - Double Surface Treatment with Granular A	\$33	6	12	72